

April 3-6, 2024 Storm Photos

Exh. GMP-DM-KB-1



Aerial view of a large tree outside the ROW on a line in Stockbridge on April 5, 2024. This is an offroad location, with multiple trees down on the length of line. Using a drone to pinpoint and assess storm damage in this cross-country location saved hours of time in restoring that line, and reduced field team exposure to potentially hazardous weather conditions.

April 3-6, 2024 Storm Photos



A large tree outside the ROW on a line in Shrewsbury on April 5, 2024, one of many trees blocking roads after the Nor'easter.

April 3-6, 2024 Storm Photos




A large tree outside the ROW, on a line in the Mendon/Killington area on Thursday, April 4, 2024.

April 3-6, 2024 Storm Photos



Another large tree outside the ROW in the Mendon/Killington area during the Nor'easter on April 4, 2024.

April 3-6, 2024 Storm Photos



Poultney area; 20" bar and still had to crosscut it. Off road distribution climbing crew that is a regular crew on our system.

April 3-6, 2024 Storm Photos



A large tree down on a line in Lincoln, April 5, 2024.

April 3-6, 2024 Storm Photos



A healthy tree down on a line in Moretown, April 4, 2024.

April 3-6, 2024 Storm Photos



A healthy white pine tree down on a line in Brandon, April 6, 2024.

April 3-6, 2024 Storm Photos



A large tree blocks a road in Middletown, April 6, 2024.

April 3-6, 2024 Storm Photos



A healthy tree trunk is visible on April 5, 2024, as a crew in Waterbury works to remove a tree torn down by the Nor'easter.

April 3-6, 2024 Storm Photos



A large tree fell from outside the ROW onto a line and blocked the road in Newfane on April 4, 2024.

April 3-6, 2024 Storm Photos



A large tree down on lines in Stamford on April 4, 2024.

April 3-5, 2024 Storm Photos



A restoration field team member standing among downed trees and line at the Townshend Dam in Townshend, following the April Nor'easter.

April 3-6, 2024 Storm Photos



A large tree outside the ROW down on lines in Chittenden, April 4, 2024.

April 3-6, 2024 Storm Photos



A large tree from outside the ROW tore down lines in Bennington, April 4, 2024.

April 3-6, 2024 Storm Photos



Trees from outside the ROW are down and blocking a road in Bethel on April 5, 2024.

April 3-6, 2024 Storm Photos



Healthy pine from outside the ROW in Wardsboro is down on lines, blocking a road on April 4, 2024.

April 3-6, 2024 Storm Photos



Healthy tree from outside the ROW blocks the road and has taken down a line in Wardsboro on April 4, 2024.

April 3-6, 2024 Storm Photos



A tall tree from outside the ROW is down on a line in Chittenden on April 4, 2024.