

**Q.NS.DPS.1-13.** Was the Mountain View Cemetery parking lot plowed when you conducted your site visit? If not, please explain the road and walkway conditions at the cemetery viewpoints you included in your analysis and identify where you parked.

**A.NS.DPS.1-13.** There was no vehicular access to the Mountain View Cemetery on the date of the field visit (February 27, 2026). Field representatives from EDR parked at 2534 Vermont Route 100, Lowell, VT 05847, walked south on Route 100 and then east on Route 58 to access the cemetery. The snow was deep and untrodden, so field representatives used snowshoes to access the site.

Person(s) Responsible for Response: Gordin Perkins

Title of Person(s): Visualization Practice Leader

Date: May 6, 2026